



PORSCHE

Press release

20 December 2018

Re-programming of control unit for the electric power steering

Porsche recalls Panamera models to the workshops

Stuttgart, Germany. Porsche is requesting that the current generation of Panamera vehicles are brought in to workshops. The control unit on the affected vehicles' electric power steering is to be re-programmed. There are 74,585 vehicles affected worldwide, produced between 21 March 2016 and 6 December 2018.

A software error means that there is a possibility that the electric power steering will occasionally be unavailable for a limited period. If this happens, increased force is then required for steering. To avoid this, the associated control unit needs to be re-programmed with an updated data record as a precautionary measure.

Affected customers are being contacted in writing and asked to attend their Porsche Centre as soon as possible. The workshop visit will take around an hour, and is free of charge for customers.

Image material available in the Porsche Newsroom (newsroom.porsche.de) and in the Porsche media database (presse.porsche.de).